

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2008 Levee Inspection Results

Reclamation District No. 0524

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

Reclamation District No. 0524

Waterway		Bank	Unit Miles
Unit No. 01 San Joaquin River		Left	6.30

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	4/2/2008			
DWR Inspector	Richard Willoughby			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 San Joaquin River						Left	6.30	04/02/2008		Richard Willoughby	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	6.26	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.941132 ° -121.346457 °	37.870442 ° -121.329823 °		1
2	0.00	6.26	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.941130 ° -121.346455 °	37.870442 ° -121.329823 °		2
3	0.22	0.22	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	37.938890 ° -121.343657 °	37.938890 ° -121.343657 °		3
4	0.36	0.36	Earthen Levee	Encroachments	LS	M	Garbage	37.938338 ° -121.341290 °	37.938338 ° -121.341290 °	Y	15
5	0.38	0.39	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.938527 ° -121.340887 °	37.938553 ° -121.340778 °	Y	4
6	0.39	0.43	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.938555 ° -121.340870 °	37.938642 ° -121.339990 °		5
7	0.48	0.49	Earthen Levee	Erosion / Bank Caving	WS	U	Schedule repair of erosion site prior to the next inspection.	37.938693 ° -121.339063 °	37.938693 ° -121.338993 °	Y	6
8	0.51	0.52	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.938682 ° -121.338518 °	37.938657 ° -121.338425 °	Y	7
9	0.53	0.54	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.938623 ° -121.338182 °	37.938617 ° -121.338045 °		8
10	0.58	0.59	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.938512 ° -121.337335 °	37.938495 ° -121.337212 °		9
11	0.63	0.63	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	37.938247 ° -121.336503 °	37.938247 ° -121.336503 °		10
12	0.63	0.64	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.938247 ° -121.336503 °	37.938197 ° -121.336405 °		11
13	0.64	0.64	Earthen Levee	Crown Surface / Depressions / Rutting	CR	U	Regrade the crown roadway for proper drainage.	37.938198 ° -121.336407 °	37.938198 ° -121.336407 °	Y	12
14	0.65	0.66	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.938105 ° -121.336288 °	37.938023 ° -121.336173 °	Y	13
15	0.68	0.68	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.937808 ° -121.335913 °	37.937808 ° -121.335913 °	Y	14
16	0.81	0.81	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.936217 ° -121.334698 °	37.936217 ° -121.334698 °		16
17	1.01	1.03	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.935098 ° -121.331645 °	37.935018 ° -121.331248 °		17
18	1.09	1.09	Earthen Levee	Slope Stability	LS	M	Repair slope instability.	37.934645 ° -121.330310 °	37.934645 ° -121.330310 °	Y	18
19	1.14	1.17	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	37.934118 ° -121.329657 °	37.933775 ° -121.329305 °		19

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 01 San Joaquin River							Left	6.30	04/02/2008	Richard Willoughby	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	1.25	1.25	Earthen Levee	Encroachments	LS	M	Garbage	37.932665 ° -121.328808 °	37.932665 ° -121.328808 °	Y	20
21	1.32	1.33	Earthen Levee	Erosion / Bank Caving	WS	M	Schedule repair of erosion site prior to the next inspection.	37.931858 ° -121.328308 °	37.931692 ° -121.328282 °	Y	21
22	1.41	1.42	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.930575 ° -121.328098 °	37.930420 ° -121.328245 °		22
23	1.56	1.74	Earthen Levee	Encroachments	LS	CO	Landscaping	37.928352 ° -121.328307 °	37.926497 ° -121.326248 °	Y	23
24	1.62	1.62	Earthen Levee	Crown Surface / Depressions / Rutting	CR	U	Regrade the crown roadway for proper drainage.	37.927658 ° -121.327865 °	37.927658 ° -121.327865 °		24
25	1.62	1.63	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	37.927635 ° -121.327812 °	37.927540 ° -121.327648 °		25
26	1.63	1.66	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.927507 ° -121.327593 °	37.927295 ° -121.327298 °		26
27	1.71	1.77	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.926728 ° -121.326597 °	37.926142 ° -121.325972 °		27
28	1.75	1.76	Earthen Levee	Encroachments	LS	U	Garbage	37.926387 ° -121.326148 °	37.926240 ° -121.326063 °	Y	28
29	1.96	1.98	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.923685 ° -121.324235 °	37.923493 ° -121.324167 °		29
30	2.17	2.18	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.921383 ° -121.322043 °	37.921300 ° -121.321902 °		30
31	2.22	2.28	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.920992 ° -121.321373 °	37.920505 ° -121.320485 °		31
32	2.29	2.31	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	37.920372 ° -121.320230 °	37.920273 ° -121.320022 °		32
33	2.32	2.35	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.920075 ° -121.319778 °	37.919702 ° -121.319700 °		33
34	2.34	2.35	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.919885 ° -121.319713 °	37.919703 ° -121.319702 °		34
35	2.46	2.50	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.918628 ° -121.320817 °	37.918438 ° -121.321452 °		36
36	2.47	2.48	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	37.918575 ° -121.320980 °	37.918515 ° -121.321110 °		35
37	2.52	2.52	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	37.918345 ° -121.321765 °	37.918302 ° -121.321923 °		37
38	2.53	2.53	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	37.918287 ° -121.321980 °	37.918287 ° -121.321980 °		38

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 San Joaquin River						Left	6.30	04/02/2008		Richard Willoughby	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	2.54	2.54	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.918242 ° -121.322125 °	37.918187 ° -121.322247 °		39
40	2.56	2.56	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	37.918047 ° -121.322415 °	37.918047 ° -121.322415 °		40
41	2.59	2.59	Earthen Levee	Encroachments	LS	M	Garbage	37.917673 ° -121.322718 °	37.917673 ° -121.322718 °		41
42	2.59	2.60	Earthen Levee	Encroachments	LS	CO	Buildings	37.917673 ° -121.322723 °	37.917555 ° -121.322778 °		42
43	2.66	2.66	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	37.916780 ° -121.322095 °	37.916780 ° -121.322095 °		43
44	2.71	2.73	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.916180 ° -121.322165 °	37.915947 ° -121.322357 °		44
45	2.74	2.83	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.915813 ° -121.322485 °	37.914963 ° -121.323605 °		45
46	2.78	2.79	Earthen Levee	Encroachments	LS	PO	Landscaping	37.915285 ° -121.322813 °	37.915175 ° -121.322983 °	Y	46
47	2.79	2.81	Earthen Levee	Slope Stability	LS	M	Repair the levee slope damaged by vehicle traffic and prevent access where possible.	37.915173 ° -121.322982 °	37.915098 ° -121.323183 °		47
48	2.82	2.82	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	37.915022 ° -121.323443 °	37.915022 ° -121.323443 °		48
49	2.88	2.88	Earthen Levee	Vegetation	LS	U	Elderberries are blocking visibility and flood fight capability.	37.914427 ° -121.324198 °	37.914427 ° -121.324198 °		49
50	2.93	2.95	Earthen Levee	Encroachments	LS	M	Prunings	37.913767 ° -121.324427 °	37.913503 ° -121.324488 °		50
51	2.96	2.96	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.913415 ° -121.324503 °	37.913415 ° -121.324503 °		51
52	3.37	3.40	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.907645 ° -121.325442 °	37.907157 ° -121.325408 °		52
53	3.39	3.45	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	37.907283 ° -121.325432 °	37.906503 ° -121.325002 °		53
54	3.43	3.49	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.906747 ° -121.325248 °	37.906192 ° -121.324543 °		54
55	3.45	3.45	Earthen Levee	Encroachments	LS	M	Garbage	37.906503 ° -121.325002 °	37.906503 ° -121.325002 °		55
56	3.47	3.49	Earthen Levee	Encroachments	LS	M	Prunings	37.906295 ° -121.324730 °	37.906192 ° -121.324545 °		56
57	3.54	3.64	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	37.905638 ° -121.323892 °	37.904430 ° -121.324570 °		57

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 01 San Joaquin River						Left	6.30	04/02/2008		Richard Willoughby	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
58	3.68	3.68	Earthen Levee	Slope Stability	WS	M	Repair the levee slope damaged by foot traffic and prevent access where possible.	37.904113 ° -121.325080 °	37.904113 ° -121.325080 °		58
59	3.82	3.82	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.902417 ° -121.326482 °	37.902417 ° -121.326482 °		59
60	3.88	4.02	Earthen Levee	Encroachments	WS	M	Prunings	37.901582 ° -121.326547 °	37.899602 ° -121.326685 °		60
61	3.89	3.89	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.901463 ° -121.326528 °	37.901463 ° -121.326528 °		61
62	3.89	4.01	Earthen Levee	Encroachments	LS	M	Equipment	37.901375 ° -121.326507 °	37.899745 ° -121.326630 °		62
63	4.05	4.05	Earthen Levee	Encroachments	LS	M	Garbage	37.899127 ° -121.326938 °	37.899127 ° Y -121.326938 °		63
64	4.08	4.13	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.898832 ° -121.327092 °	37.898090 ° -121.327457 °		64
65	4.40	4.62	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.894587 ° -121.329253 °	37.891655 ° -121.328468 °		65
66	4.64	4.64	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	37.891365 ° -121.328680 °	37.891365 ° -121.328680 °		67
67	4.64	4.64	Earthen Levee	Encroachments	LS	M	Garbage	37.891428 ° -121.328642 °	37.891428 ° Y -121.328642 °		66
68	5.24	5.24	Earthen Levee	Encroachments	LS	M	Prunings	37.883657 ° -121.332132 °	37.883657 ° -121.332132 °		68
69	5.83	6.07	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.875487 ° -121.332995 °	37.872893 ° -121.331097 °		69
70	5.84	5.84	Earthen Levee	Encroachments	LS	M	Prunings	37.875370 ° -121.333052 °	37.875370 ° -121.333052 °		70
71	5.87	5.87	Earthen Levee	Encroachments	CR	M	Pipe	37.875002 ° -121.333222 °	37.875002 ° Y -121.333222 °		71
72	5.87	5.87	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	37.874983 ° -121.333225 °	37.874983 ° -121.333225 °		72
73	5.92	5.92	Earthen Levee	Encroachments	CR	M	Pipe	37.874240 ° -121.333180 °	37.874240 ° Y -121.333180 °		73
74	5.92	5.92	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.874240 ° -121.333185 °	37.874165 ° Y -121.333155 °		74
75	5.92	5.94	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	37.874240 ° -121.333187 °	37.874002 ° -121.333027 °		75

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	4
Start Levee Mile	0.36
End Levee Mile	0.36
Location	
Category	Earthen Levee
Item	Encroachments
Garbage pile at landward toe at LM 0.36	



Levee Mile Report Line	5
Start Levee Mile	0.38
End Levee Mile	0.39
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Minor erosion from LM 0.38 to 0.39	



Levee Mile Report Line	7
Start Levee Mile	0.48
End Levee Mile	0.49
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Major erosion from LM 0.48 to 0.49	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	8
Start Levee Mile	0.51
End Levee Mile	0.52
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Erosion from LM 0.51 to 0.52	



Levee Mile Report Line	13
Start Levee Mile	0.64
End Levee Mile	0.64
Location	
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Large hole 3 x 3 on levee crown near waterside shoulder at LM 0.64	



Levee Mile Report Line	14
Start Levee Mile	0.65
End Levee Mile	0.66
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Erosion from LM 0.65 to 0.66	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	15
Start Levee Mile	0.68
End Levee Mile	0.68
Location	
Category	Earthen Levee
Item	Vegetation
Bamboo on waterward slope at LM 0.68	



Levee Mile Report Line	18
Start Levee Mile	1.09
End Levee Mile	1.09
Location	
Category	Earthen Levee
Item	Slope Stability
Landward slope damage at LM 1.09	



Levee Mile Report Line	20
Start Levee Mile	1.25
End Levee Mile	1.25
Location	
Category	Earthen Levee
Item	Encroachments
Concrete rubble with rebar on landward shoulder at LM 1.25	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	21
Start Levee Mile	1.32
End Levee Mile	1.33
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving
Erosion from LM 1.32 to 1.33	



Levee Mile Report Line	23
Start Levee Mile	1.56
End Levee Mile	1.74
Location	
Category	Earthen Levee
Item	Encroachments
Overgrown landscaping on landward slope from LM 1.56 to 1.74	



Levee Mile Report Line	28
Start Levee Mile	1.75
End Levee Mile	1.76
Location	
Category	Earthen Levee
Item	Encroachments
Garbage on landward toe from LM 1.75 to 1.76	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	46
Start Levee Mile	2.78
End Levee Mile	2.79
Location	
Category	Earthen Levee
Item	Encroachments
Landscaping (Cactus) on landward slope from LM 2.78 to 2.79	



Levee Mile Report Line	63
Start Levee Mile	4.05
End Levee Mile	4.05
Location	
Category	Earthen Levee
Item	Encroachments
Garbage at landward toe at LM 4.05	



Levee Mile Report Line	67
Start Levee Mile	4.64
End Levee Mile	4.64
Location	
Category	Earthen Levee
Item	Encroachments
Garbage at landward toe next to ramp at LM 4.64	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	71
Start Levee Mile	5.87
End Levee Mile	5.87
Location	
Category	Earthen Levee
Item	Encroachments
Abandoned pipe at LM 5.87 wateside view	



Levee Mile Report Line	71
Start Levee Mile	5.87
End Levee Mile	5.87
Location	
Category	Earthen Levee
Item	Encroachments
Abandoned pipe at LM 5.87 landside view	



Levee Mile Report Line	73
Start Levee Mile	5.92
End Levee Mile	5.92
Location	
Category	Earthen Levee
Item	Encroachments
Abandoned pipe at LM 5.92 wateside view	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

Reclamation District No. 0524

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 San Joaquin River	Left	6.30	04/02/2008	Richard Willoughby

Levee Mile Report Line	74
Start Levee Mile	5.92
End Levee Mile	5.92
Location	
Category	Earthen Levee
Item	Erosion / Bank Caving

Erosion at waterward toe at LM 5.92



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected